


www.jyebao.com.tw


BMA3205S-S402

BMA Plug Solder Clamp For RG402 Flexible; 18GHz VSWR 1.2*

50Ω







- 1. Precision connector up to 18GHz.
- 2. Solder clamp design ensures a sturdy connector/cable connection.
- 3. Manufacturing low loss high frequency RF assemblies requires expertise. *Using 5003

MOUNTING HOLE

Parts	Material	Plating (Micro-inch)		
Body	Stainless Steel	Passivated		
Contact Pin	Beryllium Copper	Gold 4 Over Nickel-Phosphorus Alloy 80 Over Copper 20		
Insulator	Teflon			
Gasket	Silicone			
Lock Washer	Stainless Steel	Passivated		
Hex Nut	Stainless Steel	Passivated		
Solder Ferrule	Brass	Gold 4 Over Nickel-Phosphorus Alloy 80 Over Copper 20		
Clamp Nut	Stainless Steel	Passivated		

Suitable Cables: 5003; SS402; .141Flexible; Multiflex.141; T-Flex 402; Multibend 402; .141SRF-W-P-50-F

ВМА		BMA3205S-S402			
Interface					
MIL-STD-348B	'				
Electrical Data					
Impedance	I	50Ω			
Frequency range		DC to 18GHz			
VSWR		≦1.2 (DC to 18GHz)			
Insertion loss		$\leq 0.03 \text{ x} \sqrt{\text{f(GHz)}} \text{dB}$			
Insulation resistance		≥5000MΩ			
Contact resistance inner cor	nductor	≦2mΩ			
Contact resistance outer cor	nductor	≦2mΩ			
Dielectric withstanding volta	ge (at sea level)	1500 V rms			
Working voltage (at sea leve))	1000 V rms			
Mechanical Data					
Engagement force	ı	≦3 lbs			
Disengagement force		≦1.5 lbs			
Contact captivation-axial		≧6.1 lbs			
Durability (mating)		≥1000			
Environmental Data					
Temperature range		-65°C to+165°C			
Thermal shock		MIL-STD-202, Method 107, Condition B			
Moisture resistance		MIL-STD-202, Method 106			
Corrosion		MIL-STD-202, Method 101, Condition B			
RoHS		Compliant			
Tooling					
	•				

Notice: JYEBAO reserves the right to make modifications deemed appropriate.

JYE BAO CO., LTD. CABLE ASSEMBLY RECOMMENDATION

BMA3205S-S402		DATE	2020/05/20	REV	_			
А	В		С	,				
	0							
BODY	SOLE FERR		CLAMP NUT					
DIAGRAM	ASSEMBLY INSTRUCTION							
SPC	Step 1: STRIP AS SHOWN.							
\ \	TIN DIP	Step 2: TIN DIP S	PC BRAID.					
S B X	Step 3: SLIDE NUT " D " AND SOLDER FERRULE " C " OVER THE CABLE. Step 4: SOLDER IN " X ".							
CUT EXCESS BRA	ID & TEFLON 7	OF THE S	Y ANY EXCESS BRAID AN OLDER FERRULE. TER CONDUCTOR TO LEN		CKING OUT			
	SHARPEN -	Step 7: SHARPEN CENTER CONDUCTOR TIP.						
	Step 8: FINALLY SCREW NUT " C " ON THE CONNECTOR BODY " A ".							
This part number complies with RoHS. Notice: JYEBAO reserves the right to make modifications deemed appropriate.								
	CKED		DRAWING	Albert				

BMA3205S-S402

S11

