


N3200BA-0215

N Plug Clamp

50Ω



Parts	Material	Plating (Micro-inch)
Nut	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50
Braid Clamp	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50
Washer	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50
Insulator	Teflon	
Center Pin	Brass	Gold 5 Over Nickel 50 Over Copper 50
Retainer Ring	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50
Gasket	Silicon	
Contact Body	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50
Body	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50
Coupling Nut	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50

Weight:

Suitable Cables: RG215

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.

CABLE ASSEMBLY INSTRUCTION

N3200BA-0215

JYE BAO CO., LTD.


N3200BA-0215

DATE

2014/04/29

REV

—



BODY



INSULATOR



CONTACT PIN



INSULATOR



WASHER



BRAID CLAMP




GASKET



WASHER



NUT




NUT

DIAGRAM


ASSEMBLY INSTRUCTION




Step 1: STRIP AS SHOWN.




Step 2: SLIDE NUT "J" · NUT "I" · WASHER "H" · GASKET "G" AND BRAID CLAMP "F" OVER CABLE.




Step 3: WRAP THE BRAIDING OVER "F".



Step 4: STRIP AS SHOWN.



Step 5: SLIDE PREPARED CABLE INTO WASHER "E" AND TEFLON "D".
Step 6: PUT CONTACT PIN "C" ON CENTER CONDUCTOR AND SOLDER OR CRIMP IN "Y".
(USE 2.55mm/0.100inch HEX SECTION OF INSERT-C IF CRIMPED)



Step 7: SLIDE TEFLON "B" INTO CONNECTOR BODY "A".
Step 8: SCREW "I" ON THE CONNECTOR BODY "A".
Step 9: SCREW "J" ON THE NUT "I".

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.