


7/16-3200B-7/8A

7/16 Plug Clamp For 7/8"
5GHz VSWR 1.2

50Ω



NOTE : For 7/8" Foam Dielectric Cable

Parts	Material	Plating (Micro-inch)
Gasket	Silicone	
Nut	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50
Contact Body	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50
Contact Pin	Brass	Gold 4 Over Nickel-Phosphorus Alloy 80 Over Copper 20
Insulator	Teflon	
Body	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50
Coupling Nut	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50

Weight: 224.36 g
Suitable Cables: EC5-50 ; LDF5-50A ; RF7/8"BHF

This part number complies with RoHS.














Notice: JYEBAO reserves the right to make modifications deemed appropriate.

7/16	7/16-3200B-7/8A																				
<div data-bbox="167 344 568 389" style="border: 1px solid black; padding: 2px;">Interface</div> <p>IEC 60169-4</p>																					
<div data-bbox="167 465 568 510" style="border: 1px solid black; padding: 2px;">Electrical Data</div> <table border="0" style="width: 100%;"> <tr> <td style="width: 50%;">Impedance</td> <td style="width: 50%;">50Ω</td> </tr> <tr> <td>Frequency range</td> <td>DC to 5GHz</td> </tr> <tr> <td>VSWR</td> <td>≦ 1.2 (DC to 5GHz)</td> </tr> <tr> <td>Insertion loss</td> <td>≦ 0.05dB</td> </tr> <tr> <td>Insulation resistance</td> <td>≧ 10000MΩ</td> </tr> <tr> <td>Contact resistance inner conductor</td> <td>≦ 0.4mΩ</td> </tr> <tr> <td>Contact resistance outer conductor</td> <td>≦ 1.5mΩ</td> </tr> <tr> <td>Dielectric withstanding voltage (at sea level)</td> <td>4000 V rms</td> </tr> <tr> <td>Working Voltage (at sea level)</td> <td>2700 V rms</td> </tr> <tr> <td>Rf leakage</td> <td>≧ 128dB to 1GHz</td> </tr> </table>		Impedance	50Ω	Frequency range	DC to 5GHz	VSWR	≦ 1.2 (DC to 5GHz)	Insertion loss	≦ 0.05dB	Insulation resistance	≧ 10000MΩ	Contact resistance inner conductor	≦ 0.4mΩ	Contact resistance outer conductor	≦ 1.5mΩ	Dielectric withstanding voltage (at sea level)	4000 V rms	Working Voltage (at sea level)	2700 V rms	Rf leakage	≧ 128dB to 1GHz
Impedance	50Ω																				
Frequency range	DC to 5GHz																				
VSWR	≦ 1.2 (DC to 5GHz)																				
Insertion loss	≦ 0.05dB																				
Insulation resistance	≧ 10000MΩ																				
Contact resistance inner conductor	≦ 0.4mΩ																				
Contact resistance outer conductor	≦ 1.5mΩ																				
Dielectric withstanding voltage (at sea level)	4000 V rms																				
Working Voltage (at sea level)	2700 V rms																				
Rf leakage	≧ 128dB to 1GHz																				
<div data-bbox="167 1057 568 1102" style="border: 1px solid black; padding: 2px;">Mechanical Data</div> <table border="0" style="width: 100%;"> <tr> <td style="width: 50%;">Recommended coupling nut torque</td> <td style="width: 50%;">260 inch lbs</td> </tr> <tr> <td>Coupling proof torque</td> <td>310 inch lbs</td> </tr> <tr> <td>Coupling nut retention force</td> <td>≧ 221 lbs</td> </tr> <tr> <td>Contact captivation-axial</td> <td>≧ 45 lbs</td> </tr> <tr> <td>Durability (mating)</td> <td>≧ 500</td> </tr> </table>		Recommended coupling nut torque	260 inch lbs	Coupling proof torque	310 inch lbs	Coupling nut retention force	≧ 221 lbs	Contact captivation-axial	≧ 45 lbs	Durability (mating)	≧ 500										
Recommended coupling nut torque	260 inch lbs																				
Coupling proof torque	310 inch lbs																				
Coupling nut retention force	≧ 221 lbs																				
Contact captivation-axial	≧ 45 lbs																				
Durability (mating)	≧ 500																				
<div data-bbox="167 1411 568 1456" style="border: 1px solid black; padding: 2px;">Environmental Data</div> <table border="0" style="width: 100%;"> <tr> <td style="width: 50%;">Temperature range</td> <td style="width: 50%;">-65°C to +165°C</td> </tr> <tr> <td>Thermal shock</td> <td>MIL-STD-202, Method107, Condition B</td> </tr> <tr> <td>Moisture resistance</td> <td>MIL-STD-202, Method106</td> </tr> <tr> <td>Corrosion</td> <td>MIL-STD-202, Method101, Condition B</td> </tr> <tr> <td>RoHS</td> <td>Compliant</td> </tr> </table>		Temperature range	-65°C to +165°C	Thermal shock	MIL-STD-202, Method107, Condition B	Moisture resistance	MIL-STD-202, Method106	Corrosion	MIL-STD-202, Method101, Condition B	RoHS	Compliant										
Temperature range	-65°C to +165°C																				
Thermal shock	MIL-STD-202, Method107, Condition B																				
Moisture resistance	MIL-STD-202, Method106																				
Corrosion	MIL-STD-202, Method101, Condition B																				
RoHS	Compliant																				
<div data-bbox="167 1765 568 1809" style="border: 1px solid black; padding: 2px;">Tooling</div> <p>SUHNER QUICK-FIT 74 Z-0-23-13 Torque Wrench</p>																					

Notice: JYEBAO reserves the right to make modifications deemed appropriate.

JYE BAO CO., LTD.

CABLE ASSEMBLY INSTRUCTION

7/16-3200B-7/8A	DATE	2018/06/01	REV	—
 <p style="text-align: center;">A</p> <p style="text-align: center;">BODY</p>	 <p style="text-align: center;">B</p> <p style="text-align: center;">CONTACT BODY + GASKET</p>	 <p style="text-align: center;">C</p> <p style="text-align: center;">FERRULE</p>		
DIAGRAM	ASSEMBLY INSTRUCTION			
	Step 1: Cut cable with saw.			
	Step 2: Strip cable jacket - outer conductor and dielectric with SUHNER QUICK-FIT 74 Z-0-23-13.			
	Step 3: Check for any metal shavings on dielectric after stripping.			
	Step 4: Strip cable jacket with a sharp blade.			
	Step 5: Cut-off the center conductor protruding out off the insulation with a sharp blade. form a chamfered edge on the center conductor to eliminate burrs and sharp edges. Note: no rough edge and shavings remains on the insulation.			
	Step 6: Slide gasket "c" over cable.			
	Step 7: Insert contact body "B" at a straight angle onto the prepared cable. Do not rotate.			
	Step 8: Slowly slide connector body "A" onto contact body "B". To prevent damaging the contact pin be careful not to rotate "A".			
	Step 9: Set and fix the connector body "A" onto the wrench fixture and hold the cable fixed by hand. Step 10: Use a torque wrench to rotate (clockwise) the contact body "B" while connector body "A" and cable are kept in a fixed position. sufficiently tighten "B" into "A" within the required torque force (27~32.5Nm).			
	Step 11: Check if the gap between connector body "A" and contact body "B" is 1.0 ± 0.15 mm. After completing the assembly process, endorse the finished product to QC engineering department for final electrical testing.			

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.

APPROVED

CHECKED

DRAWING

Albert