


TNC3200B-0011

TNC Plug Clamp

75Ω



Parts	Material	Plating (Micro-inch)
Nut	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50
Washer	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50
Gasket	Silicon	
Braid Clamp	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50
Spring	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50
Contact Pin	Brass	Gold 3 Over Nickel 50 Over Copper 50
Insulator	Teflon	
Body	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50
Coupling Nut	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50

Weight:










Suitable Cables: RG11

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.

JYE BAO CO., LTD.

CABLE ASSEMBLY INSTRUCTION

TNC3200B-0011			DATE	2016/04/18		REV	—							
A			B		C		D		E		F		G	
														
BODY			CONTACT PIN		WASHER		BRAID CLAMP		GASKET		WASHER		NUT	
DIAGRAM							ASSEMBLY INSTRUCTION							
							Step 1: STRIP AS SHOWN.							
							Step 2: SLIDE NUT " G " 、 WASHER " F " 、 GASKET " E " AND BRAID CLAMP " D " OVER CABLE.							
							Step 3: WRAP THE BRAIDING OVER " D ".							
							Step 4: STRIP AS SHOWN.							
							Step 5: PUT WASHER " C " AND CONTACT PIN " B " ON CENTER CONDUCTOR. SOLDER IN " Y ".							
							Step 6: FINALLY SCREW NUT " G " ON THE CONNECTOR BODY " A ".							
This part number complies with RoHS. Notice: JYEBAO reserves the right to make modifications deemed appropriate.														
APPROVED				CHECKED				DRAWING				Albert		