



MCX0420D-0316

Terminal Crimp For P.C.B. Mount



MOUNTING HOLE :



| Parts   | Material | Plating (Micro-inch)                 |
|---------|----------|--------------------------------------|
| Ferrule | Brass    | Gold 5 Over Nickel 50 Over Copper 50 |
| Body    | Brass    | Gold 5 Over Nickel 50 Over Copper 50 |

Weight:






Suitable Cables: RD316, RG316D-E, RD316-FEP

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.

# JYE BAO CO., LTD.

## CABLE ASSEMBLY INSTRUCTION

|                                                                                                                     |  |                                                                                                                     |            |         |   |
|---------------------------------------------------------------------------------------------------------------------|--|---------------------------------------------------------------------------------------------------------------------|------------|---------|---|
| MCX0420D-0316                                                                                                       |  | DATE                                                                                                                | 2017/03/27 | REV     | — |
| A                                                                                                                   |  | B                                                                                                                   |            |         |   |
|                                    |  |                                   |            |         |   |
| BODY                                                                                                                |  | FERRULE                                                                                                             |            |         |   |
| DIAGRAM                                                                                                             |  | ASSEMBLY INSTRUCTION                                                                                                |            |         |   |
|                                   |  | Step 1: STRIP AS SHOWN.<br>Step 2: TIN DIP.                                                                         |            |         |   |
|                                  |  | Step 3: SLIDE FERRULE " B " OVER CABLE.                                                                             |            |         |   |
|                                  |  | Step 4: LOOSEN BRAIDING AND SLIDE CONNECTOR " A " IN PLACE.                                                         |            |         |   |
|                                  |  | Step 5: SLIDE FERRULE " B " TOWARDS THE CONNECTOR " A " AND CRIMP.<br>(USE 3.3mm/0.130inch HEX SECTION OF INSERT-A) |            |         |   |
| This part number complies with RoHS.<br>Notice: JYEBAO reserves the right to make modifications deemed appropriate. |  |                                                                                                                     |            |         |   |
| APPROVED                                                                                                            |  | CHECKED                                                                                                             |            | DRAWING |   |
|                                                                                                                     |  |                                                                                                                     |            | Albert  |   |