


N6200BAS-L400

N Reverse Polarity Plug Crimp 50Ω



Parts	Material	Plating (Micro-inch)
Ferrule	Phosphor Bronze	Gold 4 Over Nickel Phosphorous Alloy 80 Over Copper 20
Gasket	Silicon	
Nut	Stainless Steel	Passivated
Contact Pin	Phosphor Bronze	Gold 4 Over Nickel Phosphorous Alloy 80 Over Copper 20
Insulator	Teflon	
Retainer Ring	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50
Contact Body	Brass	Passivated
Body	Brass	Passivated
Coupling Nut	Brass	Passivated

Weight:

Suitable Cables: JBY400; LMR400

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.

CABLE ASSEMBLY INSTRUCTION

N6200BAS-L400

JYE BAO CO., LTD.
TAIPEI TAIWAN R.O.C




DIAGRAM	ASSEMBLY INSTRUCTION
	Step 1: STRIP AS SHOWN.
	Step 2: SMEAR LUBRICANT ON INSIDE GASKET.
	Step 3: SLIDE NUT " C " IN PLACE . Step 4: WRAP THE BRAIDING OVER " C " .
	Step 5: STRIP AS SHOWN. Step 6: SHARPEN CENTER CONDUCTOR TIP.
	Step 7: PUT PIN " B " ON CENTER CONDUCTOR AND SOLDER IN " Y " .
	Step 8: FINALLY SCREW " C " ON THE CONNECTOR BODY " A " .

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.