


N8146A-L100

N Jack Crimp For Panel Receptacle

50Ω



Parts	Material	Plating (Micro-inch)
Gasket	Silicone	
Ferrule	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50
Solder Nut	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50
Insulator	Teflon	
Contact Pin	Phosphor Bronze	Gold 4 Over Nickel-Phosphorus Alloy 80 Over Copper 20
Body	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50

Weight: 35.98g
Suitable Cables: JBY100

IP67 (Mated)

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications demand appropriate.

CABLE ASSEMBLY INSTRUCTION

N8146A-L100

JYE BAO CO., LTD.




DIAGRAM	ASSEMBLY INSTRUCTION
	Step 1: STRIP AS SHOWN.
	Step 2: SLIDE "A" OVER CABLE. LOOSEN BRAIDING AND SLIDE "B" IN PLACE.
	Step 3: PUT PIN "C" AND TEFLON "D" ON CENTER CONDUCTOR AND SOLDER IN "Y".
	Step 4: SLIDE "E" INTO CONNECTOR BODY "F".
	Step 5: FINALLY SCREW "B" ON THE CONNECTOR BODY "F". Step 6: SLIDE FERRULE "A" TOWARDS "B" AND CRIMP.

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.