



SMA0400-0142

Terminal Crimp For P.C.B. Mount



MOUNTING HOLE :



Parts	Material	Plating (Micro-inch)
Ferrule	Brass	Gold 5 Over Nickel 50 Over Copper 50
Body	Brass	Gold 5 Over Nickel 50 Over Copper 50

Weight:

Suitable Cables: RG55, RG142, RG400, RG142-E

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.

CABLE ASSEMBLY INSTRUCTION

SMA0400-0142

JYE BAO CO., LTD.

SMA0400-0142

DATE


2014/04/29

REV

—

A

B




BODY


FERRULE

DIAGRAM


ASSEMBLY INSTRUCTION




Step 1: STRIP AS SHOWN.



Step 2: SLIDE FERRULE " B " OVER CABLE.



Step 3: LOOSEN BRAIDING AND SLIDE CONNECTOR " A " IN PLACE.



Step 4: SLIDE FERRULE " B " TOWARDS THE CONNECTOR " A " AND CRIMP.
(USE 5.5mm/0.217inch HEX SECTION OF INSERT-B)

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.