


SMA0401-0316

Terminal Crimp For P.C.B. Mount



| Parts   | Material | Plating (Micro-inch)                 |
|---------|----------|--------------------------------------|
| Ferrule | Brass    | Gold 5 Over Nickel 50 Over Copper 50 |
| Body    | Brass    | Gold 5 Over Nickel 50 Over Copper 50 |

Weight:

Suitable Cables: RG174, RG188, RG316, RG316-E, RG316-FEP

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.

## CABLE ASSEMBLY INSTRUCTION

SMA0401-0316

JYE BAO CO., LTD.

SMA0401-0316

DATE


2014/04/29

REV

—

A

B




BODY


FERRULE

DIAGRAM


ASSEMBLY INSTRUCTION




Step 1: STRIP AS SHOWN.



Step 2: SLIDE FERRULE " B " OVER CABLE.



Step 3: LOOSEN BRAIDING AND SLIDE CONNECTOR " A " IN PLACE.



Step 4: SLIDE FERRULE " B " TOWARDS THE CONNECTOR " A " AND CRIMP.  
(USE 3.3mm/0.130inch HEX SECTION OF INSERT-A)

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.