


SMA0401D-0316

Terminal Crimp For P.C.B. Mount



Parts	Material	Plating (Micro-inch)
Ferrule	Brass	Gold 5 Over Nickel 50 Over Copper 50
Body	Brass	Gold 5 Over Nickel 50 Over Copper 50

Weight:

Suitable Cables: RD316, RG316D-E, RD316-FEP, JBY100

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.

CABLE ASSEMBLY INSTRUCTION

SMA0401D-0316

JYE BAO CO., LTD.

SMA0401D-0316

DATE


2014/04/29

REV

—

A

B




BODY


FERRULE

DIAGRAM


ASSEMBLY INSTRUCTION




Step 1: STRIP AS SHOWN.



Step 2: SLIDE FERRULE " B " OVER CABLE.



Step 3: LOOSEN BRAIDING AND SLIDE CONNECTOR " A " IN PLACE.



Step 4: SLIDE FERRULE " B " TOWARDS THE CONNECTOR " A " AND CRIMP.
(USE 3.3mm/0.130inch HEX SECTION OF INSERT-A)

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.