


SMA0402-0141

SMA Terminal Solder
For P.C.B Mount

50Ω



Parts

Material

Plating (Micro-inch)




Body

Brass

Gold 4 Over Nickel-Phosphorus Alloy 80 Over Copper 20

JYE BAO CO., LTD.

CABLE ASSEMBLY INSTRUCTION

SMA0402-0141		DATE	2017/12/01	REV	—
A  BODY					
DIAGRAM			ASSEMBLY INSTRUCTION		
			Step 1: STRIP AS SHOWN.		
			Step 2: SHARPEN CENTER CONDUCTOR TIP. Step 3: SLIDE CONNECTOR " A " IN PLACE.		
			Step 4: USE SOLDERING FIXTURE " ST-008 ", INSERT TOOL " ST-010 " AND LOCATOR TOOL " ST-011 " TO FIX THE CONNECTOR. SOLDER IN " X ".		
This part number complies with RoHS. Notice: JYEBAO reserves the right to make modifications deemed appropriate.					
APPROVED		CHECKED		DRAWING	
				<i>Albert</i>	