



Weight:

Suitable Cables: JBY400

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.



CABLE ASSEMBLY INSTRUCTION JYE BAO CO., LTD. 7/16-8105-L400 **TAIPEI TAIWAN R.O.C** В С Α \bigcirc **BODY+NUT** SMALL PIN **FERRULE DIAGRAM** ASSEMBLY INSTRUCTION 10.8 [.425] 5.1 [.201] Step 1: STRIP AS SHOWN. Step 2: SLIDE FERRULE " C " OVER CABLE. Step 3: PUT PIN " B " ON CENTER CONDUCTOR AND SOLDER IN " Y ". С В Step 4: LOOSEN BRAIDING AND SLIDE CONNECTOR "A" IN PLACE. Step 5:SLIDE FERRULE " C " TOWARDS THE CONNECTOR " A " AND CRIMP.

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.